

Flange Mounted Load Transition Apparatus and Method

James Earl Barnett

1-618-357-9357

FIG. 1




FIG. 2

2-10




FIG. 3

FIG. 4







FIG. 5

FIG. 6



3-10

FIG. 7




FIG. 9




FIG. 8




FIG. 10




FIG. 12




FIG. 11




FIG. 14

4-10

FIG. 15




FIG. 13




FIG. 16




FIG. 17




FIG. 18




FIG. 19





FIG. 20



5-10

FIG. 21




FIG. 23




FIG. 24





FIG. 22



6-10

FIG. 25




FIG. 26 FIG. 27 FIG. 28 FIG. 29





FIG. 30




Flange Mounted Load Transition Apparatus and Method

James Earl Barnett

1-618-357-9357


FIG. 31

7-10



8-10

FIG. 32



Flange Mounted Load Transition Apparatus and Method
James Earl Barnett
1-618-357-9357

FIG. 33 $\begin{smallmatrix} 11 \\ 33 \end{smallmatrix} \searrow \begin{smallmatrix} 50 \\ 31 \end{smallmatrix}$ $\begin{smallmatrix} 113 \\ 114 \end{smallmatrix}$ 9-10




FIG. 34

111
113
32
110
11
51
52
51
52
40
135
53
136
54
42
54
121
120

10-10

FIG. 35




FIG. 36



FIG. 37




FIG. 40





FIG. 41

FIG. 38




FIG. 39



FIG. 42

